

Ajustement : principaux écarts en micromètre (1 µm = 0,001 mm)

	Jusqu'à 3 inclus	3 à 6 inclus	6 à 10	10 à 18	18 à 30	30 à 50	50 à 80	80 à 120	120 à 180	180 à 250
d10	-20	-30	-40	-50	-65	-80	-100	-120	-145	-170
	-60	-78	-98	-120	-149	-180	-220	-250	-305	-355
d11	-20	-30	-40	-50	-65	-80	-100	-120	-145	-170
	-80	-105	-130	-160	-195	-240	-290	-340	-395	-460
e7	-14	-20	-25	-32	-40	-50	-60	-72	-85	-100
	-24	-32	-40	-50	-61	-75	-90	-107	-125	-146
e8	-14	-20	-25	-32	-40	-50	-60	-72	-85	-100
	-28	-38	-47	-59	-73	-89	-106	-126	-148	-172
e9	-14	-20	-25	-32	-40	-50	-60	-72	-85	-100
	-39	-50	-61	-75	-92	-112	-134	-159	-185	-215
f6	-6	-10	-13	-16	-20	-25	-30	-36	-43	-50
	-12	-18	-22	-27	-33	-41	-49	-58	-68	-79
f7	-6	-10	-13	-16	-20	-25	-30	-36	-43	-50
	-16	-22	-28	-34	-41	-50	-60	-71	-83	-96
f8	-6	-10	-13	-16	-20	-25	-30	-36	-43	-50
	-20	-28	-35	-43	-53	-64	-76	-90	-106	-122
g5	-2	-4	-5	-6	-7	-9	-10	-12	-14	-15
	-6	-9	-11	-14	-16	-20	-23	-27	-32	-35
g6	-2	-4	-5	-6	-7	-9	-10	-12	-14	-15
	-8	-12	-14	-17	-20	-25	-29	-34	-39	-44
h5	0	0	0	0	0	0	0	0	0	0
	-4	-5	-6	-8	-9	-11	-13	-15	-18	-20
h6	0	0	0	0	0	0	0	0	0	0
	-6	-8	-9	-11	-13	-16	-19	-22	-25	-29
h7	0	0	0	0	0	0	0	0	0	0
	-10	-12	-15	-18	-21	-25	-30	-35	-40	-46
h8	0	0	0	0	0	0	0	0	0	0
	-14	-18	-22	-27	-33	-39	-46	-54	-63	-72
h9	0	0	0	0	0	0	0	0	0	0
	-25	-30	-36	-43	-52	-62	-74	-87	-100	-115
h10	0	0	0	0	0	0	0	0	0	0
	-40	-48	-58	-70	-84	-100	-120	-140	-160	-185
h11	0	0	0	0	0	0	0	0	0	0
	-60	-75	-90	-110	-130	-160	-190	-220	-250	-290
j6	+4	+6	+7	+8	+9	+11	+12	+13	+14	+16
	-2	-2	-2	-3	-4	-5	-7	-9	-11	-13
k5	+4	+6	+7	+9	+11	+13	+15	+18	+21	+24
	0	+1	+1	+1	+2	+2	+2	+3	+3	+4
k6	+6	+9	+10	+12	+15	+18	+21	+25	+28	+33
	0	+1	+1	+1	+2	+2	+2	+3	+3	+4
m5	+6	+9	+12	+15	+17	+20	+24	+28	+33	+37
	+2	+4	+6	+7	+8	+9	+11	+13	+15	+17
m6	+8	+12	+15	+18	+21	+25	+30	+35	+40	+46
	+2	+4	+6	+7	+8	+9	+11	+13	+15	+17
n6	+10	+16	+19	+23	+28	+33	+39	+45	+52	+60
	+43	+8	+10	+12	+15	+17	+20	+23	+27	+31
p6	+12	+20	+24	+29	+35	+42	+51	+59	+68	+79
	+6	+12	+15	+18	+22	+26	+32	+37	+43	+50

	Jusqu'à 3 inclus	3 à 6 inclus	6 à 10	10 à 18	18 à 30	30 à 50	50 à 80	80 à 120	120 à 180	180 à 250
D10	+60	+78	+98	+120	+149	+180	+220	+260	+305	+355
	+20	+30	+40	+50	+65	+80	+100	+120	+145	+170
F7	+16	+22	+28	+34	+41	+50	+60	+71	+83	+96
	+6	+10	+13	+16	+20	+25	+30	+36	+43	+50
G6	+8	+12	+14	+17	+20	+25	+29	+34	+39	+44
	+2	+4	+5	+6	+7	+9	+10	+12	+14	+15
H6	+6	+8	+9	+11	+13	+16	+19	+22	+25	+29
	0	0	0	0	0	0	0	0	0	0
H7	+10	+12	+15	+18	+21	+25	+30	+35	+40	+46
	0	0	0	0	0	0	0	0	0	0
H8	+14	+18	+22	+27	+33	+39	+46	+54	+63	+72
	0	0	0	0	0	0	0	0	0	0
H9	+25	+30	+36	+43	+52	+62	+74	+87	+100	+115
	0	0	0	0	0	0	0	0	0	0
H10	+40	+48	+58	+70	+84	+100	+120	+140	+160	+185
	0	0	0	0	0	0	0	0	0	0
H11	+60	+75	+90	+110	+130	+160	+190	+210	+250	+290
	0	0	0	0	0	0	0	0	0	0
H12	+100	+120	+150	+180	+210	+250	+300	+350	+400	+460
	0	0	0	0	0	0	0	0	0	0
H13	+140	180	+220	+270	+330	+390	+460	+540	+630	+720
	0	0	0	0	0	0	0	0	0	0
J7	+4	+6	+8	+10	+12	+14	+18	+22	+26	+30
	-6	-6	-7	-8	-9	-11	-12	-13	-14	-16
K6	0	+2	+2	+2	+2	+3	+4	+4	+4	+5
	-6	-6	-7	-9	-11	-13	-15	-18	-21	-24
K7	0	+3	+5	+6	+6	+7	+9	+10	+12	+13
	-10	-9	-10	-12	-15	-18	-21	-25	-28	-33
M7	-2	0	0	0	0	0	0	0	0	0
	-12	-12	-15	-18	-21	-25	-30	-35	-40	-46
N7	-4	-4	-4	-5	-7	-8	-9	-10	-12	-14
	-14	-16	-19	-23	-28	-33	-39	-45	-52	-60
N9	-4	0	0	0	0	0	0	0	0	0
	-29	-30	-36	-43	-52	-62	-74	-87	-100	-115
P6	-6	-9	-12	-15	-18	-21	-26	-30	-36	-41
	-12	-17	-21	-26	-31	-37	-45	-52	-61	-70
P7	-6	-8	-9	-11	-14	-17	-21	-24	-28	-33
	-16	-20	-24	-29	-35	-42	-51	-59	-68	-79
P9	-9	-12	-15	-18	-22	-26	-32	-37	-43	-50
	-31	-42	-51	-61	-74	-88	-106	-124	-143	-165

BACCALAURÉAT PROFESSIONNEL TECHNICIEN D'USINAGE	TECHNIQUE	Session 2020
Épreuve : U11 – Analyse et exploitation de données techniques	Code : 2006 TU ST 11 1	DT 11